J. STOCKDALE,

MILL-MAKER AND SMITH TO HIS MAJESTY,

NO. 266, HOLBORN, LONDON.

BEAN MILLS are made on an entire new Conſtruction, that will ſplit a Buſhel of Beans or Peas in ten minutes, by one perſon; to be regulated by a Screw in front: They take very little room, are worked with great eaſe, and at very ſmall expenſe.

ALSO MILLS TO GRIND

Malt,	Almonds,	Cocoa,	Roſe Leaves,	Cherry Stones,
Beans and Peas,	Pepper,	Seeds of all Sorts,	Pumice Stone,	Galls,
Wheat,	Oats for Horſes,	Charcoal,	Linſeed,	Indigo,
Barley,	Indian Corn,	Rice,	Oatmeal,	Ginger,
Hair-Powder,	Bark,	Muſtard,	Herbs of all Sorts,	Oats for Dogs.
Coffee,	Buck Wheat,	Cochineal,	Bird Seeds,	

DIRECTIONS how to FIX and MANAGE the MILLS.

PLEASE to ſcrew the Hopper of the Wheat Mill as far as it will go, quite up to the Stop, before you put the Wheat in, and leave plenty of room between the Poſt that the Mill is fixed to and the Hopper of the Mill: Take care, while fixing it, that you do not drop Chips or Nails in it. A Wheat Mill is a ſeparate Mill from others.—Price

A Bean Mill breaks Beans and Peas only.—Price

A Mill that bruiſes Oats for Horſes, breaks Barley for Pigs, and grinds Malt.—Price

Fix the Spindle of the Mill three feet one inch from the ground: If it is a Mill with a round Hopper, ſcrew it in to feed ſlower, and a little out to feed faſter; you muſt likewiſe attend to the Setting Pin for finer or coarſer—you muſt turn the Setting Pin towards you for finer, and lift up the Spring and turn the Setting Pin from you for coarſer; if a ſquare Hopper, puſh the Slide in and fill your Hopper; then as you begin to grind, draw your Slide a little out, till you bring it to feed properly; put a little of the beſt Sweet Oil in the Holes of the Ferrels that the Spindle runs in.—The Wheel is marked to the end of the Spindle it goes on.

*** *FOR READY MONEY ONLY.*

N. B. Letters (poſt paid) duly attended to.

Printed by S. GOSNELL,
Little Queen Street, Holborn.

960.